



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi




Daily Update
July 19

Repair Work

Devil's Slide (post mile 39.14)

- All cable stressing is now complete.



Stressing the last cable at level A



and the last at level D

- The temporary bench is now completely removed allowing inlets for surface drains to be installed.



Excavating for the drain inlets



Installed drain inlets

- Caltrans survey crews staked out the finish grade for the road surface.



Overview of job site today